


# Aldi Group Inspection Report

 Report No. 40-2025-05-000604-C001  
 FRI+Labelling\_DE BE NL FR PL PT  
 SP\_100%

<b>Performing TÜV Rheinland Entity</b> Durchführende TÜV Rheinland ANL:		TÜV Rheinland (Shanghai) Co., Ltd.									
Inspection Order requested at ___ % finished goods / Inspektionsauftrag bei ___ % fertiger Menge:		<input checked="" type="checkbox"/> 100 %		<input type="checkbox"/> 30 %		<input type="checkbox"/> Re-Inspection		<input type="checkbox"/> Other (please state: ___)		<input type="checkbox"/> Partly shipping	
<b>ALDI Product ID:</b>	<b>GLAS-2060225</b>	<b>P/O No.</b>	<b>N/A</b>	<b>Article No.:</b>	<b>1017057</b>	<b>SAP No.:</b>	<b>N/A</b>				
<b>Client:</b> ALDI North <b>Supplier:</b> Sänger Hauhaltsprodukte GmbH <b>Supplier Contact:</b> Ilse Sänger / Samantha Model <b>Factory:</b> Shandong JYJ Safety Products Co., Ltd. <b>Factory Contact:</b> Mr. Eason Jiang <b>Factory address:</b> Yangguang District, Banquan Town, Junan County 276000, Linyi, Shandong Sheng, China <b>Place of Inspection:</b> Yangguang District, Banquan Town, Junan County 276000, Linyi, Shandong Sheng, China <b>Date of Inspection:</b> 09 May 2025											
<b>Product Name:</b> L-M-GARDEN GLOVES LATEX, 2Pk											
<b>Country</b>	<b>Order Quantity</b>	<b>Shipment Quantity</b>	<b>Available Quantity of goods ready for inspection at factory / Verfügbare Mengen bereit für Inspektion bei dem Hersteller</b>					<b>Selected Samples</b>			
DE-Nord	188,060 sets (100%)	188,060 sets (100%)	188,060 sets (100%)					508 sets			
BE	27,540 sets (100%)	27,540 sets (100%)	27,540 sets (100%)					75 sets			
NL	14,060 sets (100%)	14,060 sets (100%)	14,060 sets (100%)					38 sets			
FR	40,020 sets (100%)	40,020 sets (100%)	40,020 sets (100%)					108 sets			
PL	8,040 sets (100%)	8,040 sets (100%)	8,040 sets (100%)					22 sets			
PT	3,520 sets (100%)	3,520 sets (100%)	3,520 sets (100%)					10 sets			
SP	14,480 sets (100%)	14,480 sets (100%)	14,480 sets (100%)					39 sets			
<b>Total</b>	<b>295,720 sets (100 %)</b>	<b>295,720 sets (100 %)</b>	<b>295,720 sets (100 %)</b>					<b>800 sets</b>			
<b>Sample Drawing - Musterteilentnahme [for external Testing / Reference, if requested]:</b>											
<b>Samples Drawn out of Cartons No.:</b>		No carton no. was found on export carton									
<b>Quantity of Samples (Total)</b>		<b>Receiver [Full Address + Contact Person]</b>					<b>Courier / Waybill No. [Photo]</b>				
--		--					--				
<b>Insp. Standards, doc.</b>	:	General Random Sample Test in accordance with ISO 2859 of visual defects (according to testing instructions chapter IV) / Stichprobenprüfung nach ISO 2859 sichtbarer Fehler (gemäß Prüfanweisungen Abschnitt IV)									
<b>Sampling Standard</b>	:	<input type="checkbox"/> General Level I <input checked="" type="checkbox"/> General Level II <input type="checkbox"/> Special Insp. Level ___									
<b>Cartons / Units of shipment:</b>	:	Total 14,327 ctns as stated by factory representative claimed.									
<b>Total number of inspected cartons:</b>	:	120 ctns	<b>Carton No.:</b>	No carton no. was found on export carton							
<b>Final Judgment</b>											
<b>Workmanship (AQL)</b>				<b>FINAL - Overall Conclusion</b> <input checked="" type="checkbox"/> <b>PASS</b> <input type="checkbox"/> <b>FAIL</b>							
<b>Defects</b>	<b>AQL</b>	<b>Allowed</b>	<b>Found</b>	<b>FRI</b>				<b>Labelling Documentation</b>			
<b>A. Critical / Kritische Fehler</b>	-	0	0	<b>FRI</b>				<b>Labelling Documentation</b>			
<b>B. Major / Bedeutende Fehler</b>	1.5	21	4	<input checked="" type="checkbox"/> <b>PASS</b>				<input checked="" type="checkbox"/> <b>PASS</b>			
<b>C. Minor / Geringe Fehler</b>	4.0	21	14	<input type="checkbox"/> <b>FAIL</b>				<input type="checkbox"/> <b>FAIL</b>			
<b>Name(s) of Inspector(s)</b>				<b>Name of Reviewer</b>							
09 May 2025    Ethan Zhang Date                      Name                      Signature				12 May 2025    Ellie Gu Date                      Name                      Signature							

This report does not release sellers/suppliers from their legal or contractual obligations with regard to the quality/quantity of this delivery, nor does it prejudice any right to claim compensation from sellers/suppliers for any apparent and/or hidden defects not detected during our random inspection or testing. The results contained in this report indicate that the samples taken from the specific shipment have passed or failed the tests and quality check points as indicated in the report. These test and check results, even if rated as "Passed," do not in any way confirm the authenticity or accuracy of the product or any declarations of conformity or trade marks on such product and/or the packaging. The inspection report does not entitle to carry the TÜV Rheinland quality mark on these or similar products.